

FIRST TRIP MONITORING

RECORDING OF FIRST TRIP OPERATION Z-FT



REFERENCE : Z-FT-CBA

AC current clamp for first trip recording.

2 scales : 10mV/A and 100mV/A

Neutrik connector for 0-10V analog inputs of the CBA-32P.



REFERENCE : Z-FT-CBV

AC current clamp for first trip recording.

2 scales : 10mV/A and 100mV/A.

Neutrik connector for +/- 10V analog inputs of the CB11 and CBV-X.

CONVERTS CURRENT TO VOLTAGE

